

M/015/041

DOGM RECEIVED  
~3/5/97



A. Gypsum mine operated by Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 1-28-97.



B. Looking southwest from the mine into a proposed expansion area called Area C, Diamond K Gypsum, Inc. in T.22S., R.9E., Section 29. 1-28-97.

M/015/041

DOC4 RECEIVED  
~3/5/97




A. Looking down the new access road to the new pit in Area B, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.



B. Looking up the new access road from the pit, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.

4/015/041  
DEGM RECEIVED  
~3/15/97



C. Closeup of the new access road, Diamond K Gypsum, Inc., plan UTU-69860 in T22S., R.9E., Section 29. 2-26-97.



D. Crawler-backhoe on the north end of the pit with a bulldozer, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.

11/015/041

DEGM RECEIVED  
13/5/97



E. Loader at the west end of the new pit, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.




F. Overburden stockpile between the loader and the crawler-backhoe, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.

M/015/041  
DOCUM RECEIVED  
13/5/97




G. New gypsum pit, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.



H. Gypsum stockpile located at the southwest corner of the pit, Diamond K Gypsum, Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.

M/015/041  
DOGM RECEIVED  
~3/5/97



- I. View of the old pit looking southwest in Area A, Diamond K Gypsum Inc., plan UTU-69860 in T.22S., R.9E., Section 29. 2-26-97.